

100 Marland Road S. Garage

View from the southwest

Page 2

New landscaping per the current proposal:

Three aspen trees (type recommended by the fire inspector)

Three lilac shrubs (type recommended by the fire inspector)



FIGURE 10