# Numismatic Property Acquisition


City Council Work Session January 23, 2017




### **Urban Trails System**



- Opportunity to connect the Rock Island Trail to the Pikes Peak Greenway
- Major missing section within the trails system
  - Rock Island Trail at Beacon Street
  - Sand Creek Trail at Las Vegas
  - Cottonwood Trail at Academy Blvd.
  - Midland Trail Ridge Road to Columbia
  - Templeton Gap Trail Greenway to Nevada
- Legacy Loop Key missing link
- America the Beautiful Millennium Trail
- Master Plan Priority since 1983





### **Recent and Current Investments in Corridor:**

UPRR Acquisition – 2015


Popcycle Bridge - 2015

2D Improvements – 2016

Legacy Loop – Trail Construction – 2016 / 2017

### Rock Island Trail: Numismatic Property





### Rock Island Trail: Numismatic Property





### Rock Island Trail Numismatic Property





Size of the Warehouse: 6,744 sq. ft.



## Rock Island Trail Numismatic Property








## Legacy Loop: Phase 1





### Legacy Loop: Project Schedule





# Acquisition Terms:



#### **Summary of Proposed Acquisition**

- Owner: American Numismatic Property
- Location 2415 Beacon Street / Tax Schedule Number 6331338011
- Parcel size: 35,000 square feet (0.8 Acres)
- Building: 6,744 square feet
- Purchase Price: \$424,900 (Appraised Value)

#### **Additional Terms of Acquisition:**

- Approval by TOPS, Parks Board, and City Council
- Standard due diligence
- Access Easement for Beacon Street
- Up to \$25,000 Relocation Expenses

# Additional Considerations:



#### **Existing Warehouse**

- Alternative: Adaptive Reuse
  - TOPS Ordinance Restrictions / Provisions
  - Cost of Adaptive Reuse
  - Request for Proposals
- Alternative: Demolition and Removal of the Existing Warehouse
  - Cost of Demolition and Reclamation of Property (Est. \$85,000)

#### **Trail Construction**

Construction costs (Est. \$120,000)

#### **Ongoing Maintenance**

- Annual Maintenance costs (Est. \$1,500 + Adopt-a-Trail Program)
- Building Maintenance cost (undetermined)